



Crewit Resourcing Limited



#JOB-2441526



Multiple Locations



No of positions : 16



Paid Position



39 hours per week



36605.00 Euro Annually



07/04/2026



05/05/2026

How to apply

Application Method :

Not available



Open your camera app & point here to view this ad online



Plant Mechanics

Application Details

In order to work in Ireland a non-EEA National, unless they are exempted, must hold a valid employment permit. Please review the [Eligibility and requirements for an employment permit](#) if you are unsure of your eligibility to apply for this vacancy.

Job Description

Multiple Locations :

- Plazamont Limited t/a Dan Morrissey and Company, Dan Morrissey Business Park, Bennekerry, Co. Carlow,
- Plazamont Limited t/a Dan Morrissey and Company, Quarry, Clonmelsh, Co. Carlow, R93 WP83
- Plazamont Limited t/a Dan Morrissey and Company, Ballyburn Upper, Castledermot, Co. Kildare,
- Plazamont Limited t/a Dan Morrissey and Company, Charles Stewart Parnell Quarry, Balleese Wood, Rathdrum, Co. Wicklow,

Our client, Plazamont Limited t/a Dan Morrissey and Company, based in Bennekerry, Co. Carlow, is currently seeking Plant Mechanics for immediate start at their facilities in Co. Carlow, Co. Kildare & Co. Wicklow.

Qualifications:

2-3 years' Plant Mechanic experience required. Mechanic Certification preferred but not essential. There are no minimum academic requirements. Further training will be provided on-the-job as required.

General Duties / Responsibilities / Experience:

To maintain, troubleshoot, repair, and service machinery and equipment used in quarries, quarrying and related activities

To ensure that all plant machinery is operating efficiently and safely, to minimize downtime, and to support the overall productivity of the plant

To perform regular maintenance checks on plant machinery, including mixers, conveyors, pumps, crushers, and batching systems.

To conduct preventative maintenance tasks to extend the life of equipment and minimize breakdowns.

To lubricate machinery, replace worn parts, and ensure all components are in good working condition.

To identify mechanical, electrical, and hydraulic issues in plant equipment and diagnose problems accurately.

To repair or replace faulty parts, ensuring that all machinery is returned to full operational capacity in a timely manner.

To perform both scheduled and emergency repairs to minimize downtime.

To ensure all work is conducted in compliance with health, safety, and environmental regulations.

To maintain accurate records of maintenance, repairs, and inspections performed on plant equipment.

Essential knowledge includes mechanical, electrical, hydraulic, and pneumatic systems, as well as the ability to diagnose and fix issues promptly to ensure smooth plant operations

Essential knowledge includes strong mechanical, electrical, and hydraulic knowledge, ability to read technical drawings, schematics, and manuals, and excellent trouble-shooting and problem solving skills

Essential skills include application of relevant health & safety and environmental legislation, performance of system checks and adjustments on machinery, and monitoring of inventory supply for required equipment

Candidates must be competent to assist in the installation and commissioning of new equipment or upgrades

Candidates must be competent to monitor stock levels of spare parts, tools, and equipment needed for maintenance and order parts and supplies as needed

A mechanic qualification or certificate is a bonus but is not mandatory

2-3 years' of proven relevant experience as a Plant Mechanic is required. Experience in the quarry industry is a plus

Annual remuneration: €36,605.00; Pay rate €18.05 per hour

Work Locations:

Dan Morrissey Business Park, Bennekerry, Co. Carlow

Quarry, Clonmelsh, Co. Carlow, R93 WP83

Ballyburn Upper, Castledermot, Co. Kildare

Charles Stewart Parnell Quarry, Balleese Wood, Rathdrum, Co. Wicklow

Number of hours work each week: 39

- **Sector:** mining and quarrying

Career Level

- Experienced [Non-Managerial]